Approved For Release 2002/10/29 . CIA-RDP63-00313A000600010081-6

!		10 × 29 July 1956	3
! :	MEMORANDUM FO	R: Special Assistant to the Director for Planning and Development	
	SUBJECT	1 Over-Age Components	
25X1A	REFERENCE	2301 (IN 42835) B. 5834 (IN 42878) C. 5835 (IN 42879)	
		memorandum same subject, dated 23 July 1958 receive me following action has been taken:	ed
25X1A		oroblem with who feels no real problem exists as long as normal ingreation procedures are followed. Ref. Comes Lockheed's reply to Ref. A. is	
25X1A 5X1A		coordinating with on this matter.	
25X1A 25X1A		has received a personal which narrowed the problem down to Fuel Sump Tanks and their components. These tanks previously had been shipped with components installed. Action has now been taken with Lockheed's concurrence to store and ship tank and auxiliary equipment has separate components. Air Frame parts previously were packed and stamped with an	
:		expiration date, however, inspections continued by Lockheed at both Warner-Robins and	25X1A
25	X1A [parts are now inspected only prior to shipment. is answering letter	25X1A
25)	X1A	this date, with a copy to Headquarters, wherein certain guidance is provided is also preparing an IHM listing to be used as a	
2	5X1A	monitor by the everseas detachments and	25X1A

Approved For Release 2002/10/29 : CIA-RDP63-00313A000600010081-6

Approved For Release 2002/10/29 : CIA-REP63-00313A000600010081-6

-2-

2. It was	Andrew 15 A	
	xinion that may	25X1A
of "continual effort" on the part subject problem.	of to rectify	25X1A
viously result from the fact that initially prior to deployment thro	the detachment was supplied ough Base Supply at	25X1A 25X1A
as to progress. Apparent evidence is that no comment has been forthouse they are following the nor	keep us advised as to the degree of the problem coming from Detachment C, probably mal procedures prevalent in the	25X1/
CFW:ms (29 July 1958)	Director of Materiel	25X1A
Dist: 0 &-Addressee cc - Dep. Dir, cy 2 Ops, cy 3 - Logs, cy 4	DPS/DCI	
	have been everly concerned, further of "continual effort" on the part subject problem. 3. The divergency between Deformer of referred to in Paragray viously result from the fact that initially prior to deployment through Records of this equipment would the A. It is the writers opinion hand and this office has requested as to progress. Apparent evidence is that no comment has been forther because they are following the nor Air Force with regard to inspection CFW:ms (29 July 1958) Dist: 0 &-Addressee cc - Dep. Dir, cy 2	have been everly concerned, furthermore, there is no evidence of "continual effort" on the part of to rectify subject problem. 3. The divergency between Detachment B's records and those of referred to in Paragraph one of your memorandum, obviously result from the fact that the detachment was supplied initially prior to deployment through Base Supply at Records of this equipment would therefore be in files. 4. It is the writers opinion that this matter is well in hand and this office has requested that keep us advised as to progress. Apparent evidence as to the degree of the problem is that no comment has been forthcoming from Detachment C, probably because they are following the normal procedures prevalent in the Air Force with regard to inspection prior to installation or use. CFW:ms (29 July 1958) Director of Materiel DPS/DCI cc - Dep. Dir, cy 2 Ops, cy 3